



Axis Pattern:

The following section will show you how to make axis pattern:


1. Create a new part or open a part you want to pattern for. We already created a simple block, so we will just open the part.



a. Click "open" on the




b. Click "Open" to open file.




now the part has been opened
in the operating window.


2. Make axis on the part to be taken as centerline to pattern.


e. Choose "Axis" from the menu.






3. Make feature to pattern with. In this sample, we will make a hole.







a. Created a hole with desired dimensions and location.


4. Make axis pattern for hole.







Pattern setting window will open.






e. Click "OK" to finish the axis pattern of the holes.





d. Turn off some pattern keys if needed.



Some holes have been turned off now.

